

## Additional Funding Request

<b>Site: NY058</b>	<b>CSS # 22135 WO-2-6027</b>
Description of Repairs	Replace Faulty Occupancy Sensor Room 219 Training Building
Diagnosis: Initial Work Order <b>CSS# 22135</b>	Door knob fell off S2 office, room #3004C, third floor of building 200
Explanation of Additional Costs for Repairs	Labor and Material to Replace defective faucet with Delta 8" Spread single handle Remove and repair faulty power pack on infer-red lighting controlling room 229 at NY0058 Work order 2-6027 CSS 22135. Electrical & Lighting materials for above repair. Incidentals to investigate above repair. Material for above.
Additional Labor Cost to Perform Repairs	$5 \times \$110.00 = \$550.00$
Additional Material Cost to Perform Repairs	\$321.41
Total Cost of Repair	\$871.14
<b>Notes:</b>	

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

## Estimate

Date	Estimate #
11/8/2019	1185

Name / Address

---

International Support Group  
9050 Pine Blvd., Suite 150  
Pembroke Pines, FL 33024