

Additional Funding Request

Site: NY023	WO# 11476 CSS # 28288
Description of Repairs	Remove and replace (2) Light fixtures in main building and OMS building boiler Rooms
Diagnosis: Initial Work Order	Repair light fixtures in training building and maintenance shop boiler room
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 hrs @ \$210.00 = \$840.00
Additional Material Cost to Perform Repairs	\$380.00
Total Cost of Repair	\$1220.00

ACAV SERVICES

January 4, 2021



ESTIMATE 010421 CSS28288

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (MAIM/OMS BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	<p>NY058</p> <p>REPLACE DEFECTIVE (2) LIGHT FIXTURES IN MAIN BUILDING AND OMS BUILDING BOILER ROOMS</p> <p>MATERIAL</p> <p>2 EA 48" LED CEILING MOUNTED LIGHT FIXTURES</p> <p>LABOR 4 HRS @ \$210.00 PER HOUR</p> <p>TOTAL</p>		<p>\$380.00</p> <p>\$840.00</p> <p>\$1220.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581