

Additional Funding Request

Site: NY058	WO# 12246 CSS # 29088
Description of Repairs	#2 Slant Finn Oil burner not working, remove and replace defective spark control module, and remove and replace defective ignition electrode
Diagnosis: Initial Work Order	Repair boiler #2 in Training Building, won't kick on
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3 Hours @ 225.00= 675.00
Additional Material Cost to Perform Repairs	200.00
Total Cost of Repair	\$875.00

ACAV SERVICES

February 23, 2021



ESTIMTE 022321 CSS29088 WO12246

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW R Linn
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BUILDING BOILER ROOM #2 SLANT FINN OIL BURNER NOT WORKING TROUBLE SHOOT SYSTEM REPLACE DEFECTIVE SPARK CONTROL MODULE REPLACE DEFECTIVE IGNITION ELECTRODE		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty	Item #	Description	Unit Price	Line Total
		LABOR 3HRS @ 225.00 PER HR		\$675.00
		MATERIAL		
		SPARK CONTROL MODULE		\$125.00
		IGNITION ELECTRODE		\$75.00
		TOTAL		\$875.00
				TOTAL \$875.00