

Additional Funding Request

Site: NY058	WO# 15891 CSS #34084
Description of Repairs	Additional Funding for further diagnostic only. Upon initial diagnostic found circuit breaker panel was opened. All breakers were checked for power. Circuit tracer was attached with the feed unable to be determined. Additional panel was investigated. All breakers have been determined to be operating correctly. All wires in Room 111 were checked for power and is currently open and no power is still present. Additional hours will be needed to perform additional diagnostic to continue to trace cause.
Diagnosis: Initial Work Order	Diagnose and Repair 3 Outlets in Room #111
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	Included incurred cost of 450.00 on initial Diagnostic, requesting 8 hrs @ 125.00= \$1000.00 For a total cost of \$1450.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1450.00 For further diagnostic only