

Over and Above Estimate

Region: 2

Location: NY058

CSS #:90045

Maximo Work Order No. 19371 **Asset#:**

Date Issued: 9/26/2022

Original Description: HVAC changeover from Cooling to Heating

Description of Repairs: The contractor will perform the HVAC Changeover for A/S to heat due to non working BMS system all controls must be set manually.

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$0	\$	\$0

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Materi al	Other cost	Total Cost	CE Factor	Total Estimate
HVAC Tech at 16 hours @ 235.00=3760.00	\$4930.00	\$0	\$	\$0	.90	\$4437.00
Heating Tech at 6 hours @ 195.00 -1170.00						

Please see attached estimate.

ACAV SERVICES

September 24, 2022



ESTIMATE 092422 CSS90045 WO19371

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW L CORBO
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BLDG PERFORM HVAC CHANGE OVER FROM A/S TO HEAT (NO WORKING BMS SYSTEM ALL CONTROLS MUST BE SET MANUALLY) LABOR HVAC TECH 16 HRS @ \$235.00 PER HOUR HEATING TECH 6 HRS @ 195.00 PER HOUR		\$3760.00
				\$1170.00
		TOTAL		\$4930.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581



Windows Boot Manager

You have encountered a problem communicating with a device connected to your computer.

This error can be caused by unplugging a removable storage device such as an external USB drive while the device is in use, or by faulty hardware such as a hard drive or CD-ROM drive that is failing. Make sure any removable storage is properly connected and then restart your computer.

If you continue to receive this error message, contact the hardware manufacturer.

File: \Boot\BCD

Status: 0xc00000e9


Info: An unexpected I/O error has occurred.


ESC=Exit

ENTER=Continue

DELL







WEISS
INSTRUMENTS



