

## Additional Funding Request

<b>Site: NY058</b>	<b>WO#20615 CSS # 91447</b>
Description of Repairs	Realign guides and adjust wheels and tension on drive chain
Diagnosis: Initial Work Order	Repair main entrance gate. Gate is stuck open.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	750.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$750.00

# ACAV SERVICES

January 9, 2023



ESTIMATE 010623 CSS91447 WO20615

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW L CORBO
Customer ID#	NY058 (MAIN GATE)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item #	Description	Unit Price	Line Total
1	1	<b>NY058 MAIN GATE</b>  <b>REPAIR MAIN ENTRANCE GATE</b> <b>REALIGN GUIDES ADJUST WHEELS</b> <b>AND TENSION ON DRIVE CHAIN</b>  <b><u>LABOR</u></b> <b>3 HRS @ \$250.00 PER HOUR</b>		
16	84	<b>TOTAL</b>		<b>\$750.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

