

Additional Funding Request

Site: NY058	WO# 21779 CSS # 93068
Description of Repairs	Remove and replace condensate pump like for like and relevel.
Diagnosis: Initial Work Order	Repair HVAC leak in Electrical room within the storage area of the training building.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	680.00
Additional Material Cost to Perform Repairs	689.13
Total Cost of Repair	\$1369.13

WORK ORDER ESTIMATE

CSS #:		93068	Work Order #: 21779			
Emergency		Urgent		Routine		
Company Name:	ISG		Facility ID:	NY058		
Contractor POC:						
Telephone No:	954-900-1095		Building/Location; (e.g., Classroom/Room #)	Building 104 - T.R. Room		
E-Mail Address:	drowe@internationalsupportgroup.com					
Assigned Technician(s):	DEEN ROWE					

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

This is a water leak not a freon leak. Unit is cooling fine. The condensate pump is not leveled and has failed. In order to remove high water pan alarm the condensate pump needs to be replaced. Also the condensate pump sitting station needs to be leveled so that there will no longer be any leaks. Once the condensate pump is replaced the unit will no longer leak. The condensate pump will be replaced like for like.

