

## Additional Funding Request

<b>Site: NY058</b>	<b>WO# 21780 CSS # 93070</b>
Description of Repairs	Remove and Replace like for like fan Motor
Diagnosis: Initial Work Order	Repair fan motor in main electrical room of training building. Motor not blowing cold air.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	680.00
Additional Material Cost to Perform Repairs	432.00
Total Cost of Repair	\$1112.00

# WORK ORDER ESTIMATE



1 Penn Plaza, Suite 1500  
New York, NY 10119  
PH: (212) 239-7711  
Fax: (212) 239-7723

COMPANY:	VISA MC AMX TAXABLE	PROPOSAL #:	CPQ-475834-1
ATTN:	International Support Group	PAGES:	4
VALID TO:			
FROM:	Chris Carlson	DATE:	4/12/2023
PROJECT:			

We are pleased to provide our Quotation for the following Vertiv products and services:

Line	Part Number	Description	Quantity	Net Price	Ext. Net price
1.0	1D19535P1S	"MOTOR .50HP 205//236-1-50/60"	1	\$360.00	\$360.00
Total Quoted Price - value for Purchase Order - Not including Freight Or Tax					

