

Date:

Region:   
FAC ID:

CSS No.:   
Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Troubleshoot lighting circuit with infrared imaging to check for "hot wires" in transformer boxes. Last electrician suggested this may locate issues with lighting circuit.

**Description of Repairs Needed:**

Labor and material to a.) Conduct an IR Scan of electrical equipment and provide report.

**Labor:**

	Labor Hrs	Labor Rate	Total
Technician (1)	8	\$ 125.00	\$ 1,000.00
			\$ -

**Material List:**

	Quantity	Cost	Total
IR Scan Report	1	\$ 1,500.00	\$ 1,500.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
IR Scanner Rental (daily)	1	\$ 1,000.00	\$ 1,000.00
		\$	-
		\$	-

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$1,000.00	\$1,500.00	\$1,000.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,500.00	\$420.00	\$210.00	\$4,130.00