

Over and Above Estimate

**Region:4**

**Location:** PA118

**CSS #:** 16738

**Maximo Work Order No:** 6864

**Asset #:** 7671, 7800 7817, 7843 7850, 7860

**Date:** 12/21/2018

**Original Description:**

Several overhead doors need repairs: Door #14 - Replace the following - both cables including stops, thimbles and sleeves (as needed), rear Shive pulleys and coil cord. Install #50 chair for shafts.

Replace one 12'2" x 24" bottom section. Door #15 - Replace the following - both cables including stops, thimbles and sleeves (as needed), remove and replace two drums, remove and replace operator and center couplers, coil cord.

Service safety edge including new safety edge kit. Repair/replace side seal. Door #3 & 12 control switches Warehouse Door - Remove and replace (1) 12'2" x 24" 591 section. Replace side seal and install pneumatic hose for sensing edge. Replace coil cord. Urgent request due to safety issue with cables. Recommended vendor is Plyler Overhead Door.

**Repairs Needed:**

Labor and materials to complete repairs on several overhead doors.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Labor/Truck	46	\$98.00	--	--	\$4,508.00
--	NA	Equipment Charge/scissor lift	--	--	--	\$580.00	\$580.00
--	NA	Various Materials (please see attached estimates for backup)	--	--	\$2,653.00	--	\$2,653.00
--	NA	CMI Coordination and Site/Task Oversight	4	\$80.00	--	--	\$320.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
50	\$4,828.00	\$2,653.00	\$580.00	\$8,061.00	102%	<b>\$8,222.22</b>

## **The Genuine. The Original.**



# MAINTENANCE & REPAIR CHECKLIST

## SUMMARY OF RECOMMENDED REPAIRS

**JOB/FACILITY NAME:**

USARC PA118

**ADDRESS:**

6467 Mike Wood Blvd.

**CITY, STATE, ZIP:**

Conneaut Lake, PA 16316

**SALESMAN SIGNATURE:**

Jesse Selman

DATE:

12/20/2018

**CUSTOMER SIGNATURE:**

DATE:

1