



Asset 6928, Traversing gear, trolley gear case leaking at the input and case seal. Needs to be repaired. Hoisting motor, the fan is missing, located next to the holding brake. Needs to be repaired. Conductor, Underground. Add a mounting bracket or replace 400' center tap. Needs to be repaired

Trolley gear case is leaking at the input and case seal. Recommend resealing gear case.

The fan is missing, located next to the holding brake. Recommend installing.

Runway does not have permanent and continuous ground. Recommend installing approx. 400' of conductor bar for permanent ground.