



Building 288. The indoor cooling unit connected to Asset5228 is squealing. I do not see an asset tag on it but I believe that per the asset list, it could be 5154 or 5155. The indoor unit is located in the data closet. Unit does not appear to have been serviced recently.

Proposal to provide and perform the following:

- Replacement of existing 2 Ton Split system with two 1-ton heads. Repair parts are no longer available. System is operational one head has noisy motor.
- Remove and properly dispose of existing split system
- Reuse existing line set, power and control wiring
- Start up and warranty

CMI Cost Estimate							
Over & Above							
PA051-227 Johnstown							
The indoor cooling unit connected							
CSS #17534 - CMI # 7558							
Prepared By: J. Bayne							
02.13.19							
P3							
			Labor			Sub	OHP
Description	Rate	Hours	Cost	Material	Tax	Total	20%
1. Repair Cost							
1.1 Labor	\$ 98.00	24					\$ 2,352.00
1.2 Material					\$ -	\$ -	\$ 90.00
1.3 Equipment							\$3,898.22
1.4 Consumables							\$ 80.00
1.5 Shipping							\$ 125.00
Sub Total Repair Cost							\$ 6,545.22
2. Initial Service Call Investigation							
2.1 Field Review at Site	\$ 98.00	2					\$ 196.00
CE Factor 102%							\$ 134.82
Grand Total							\$ 6,876.04

