



Technician labor to troubleshoot Drill Hall Thermostat that is not responding to DDC

Proposal is to provide and perform the following:

- Install new Honeywell WEB8000 module for graphical interface
- Develop database from existing ATC network devices
- One year parts and labor warranty
- Start up

CMI Cost Estimate								
Over & Above								
PA053 Johnstown								
Troubleshoot Drill Hall Thermostat								
CSS #14160 - CMI # 8172								
Prepared By: J. Bayne								
2.22.19								
P3 Routine								