



Repair by replacement, missing safety edge and head stop on drill hall door (ARC) and provide and install vinyl OH door trim on 3 OH doors (BMA and ARC) (match existing color scheme).

Proposal to furnish & install.

Materials for repair to (3) sectional doors as follows:

Asset#7746-16' electric reversing edge, (16') 3" PVC weatherstrip

Asset#7747-(44') 2" PVC weatherstrip, green

Asset#7776-(34') 2" PVC weatherstrip, green

CMI Cost Estimate								
Over & Above								
PA011 Brookville								
Repair by replacement, missing safety edge								
CSS #14265- CMI # 4928								
Prepared By: J. Bayne								
1.24.19								
Assets - 7776, 7747 & 7746								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	18						\$ 1,764.00
1.2 Material					\$ -	\$ -	\$ -	\$ 441.28
Markup 20%								\$ 88.26
1.3 Lift Charge								\$290.00
Sub Total Repair Cost								\$ 2,583.54
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	3						\$ 294.00
CE Factor 102%								\$ 57.55
Grand Total								\$ 2,935.09



PA011-01

Asset # 7746-Ovhd,Door-





