

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair the Reznor heater by replacing the relay switch. The overhead Reznor heater located in the OMS building will need the relay switch replaced per PM Tech Pat Boardman.

Description of Repairs Needed:

During replacement of the motor to the Reznor heater located in the OMS bldg, discovered that the relay switch also needed replacing. This work order is a follow up to the motor replacement in order to return the unit operational.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -

Material List:

	Quantity	Cost	Total
Reznor Fan Control (#123976)	1	\$ 146.13	\$ 146.13
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$146.13	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$346.13	\$41.54	\$20.77	\$408.43