

Date:

Region:
FAC ID:

CSS No.:
Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Repair/replace the following: three (3) lights on training center - (1) over mechanical room door, (1) by side exit to OMS and (1) over drill hall main door. There are also two high building lights that will need a lift on the drill hall portion of the building - OMS side. OMS - (4) - both main door lights are out and the 2 by the overhead doors. Recommend Cox and Kanyuck at least for the high building lights.

Description of Repairs Needed:

Supply and replacement of two (2) high flood lights and seven (7) wall pack lights. Bucket truck required to address lighting replacement needs.

Labor:	Labor Hrs	Labor Rate	Total
Cox & Kanyuck Tech (2)	8	\$ 105.00	\$ 840.00
CMI Tech (1)	2	\$ 100.00	\$ 200.00

Material List:	Quantity	Cost	Total
Sylvania 140w LED (LEDV FLOODLT 1C/140UNVD8SC2/WF/BZ	2	\$ 97.50	\$ 195.00
Wall Pack (LEDV MWLPAKN2AS030UND8SC2BZP CLR/LUM (634)	9	\$ 52.00	\$ 468.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:	Quantity	Cost	Total
Bucket Truck	4	\$ 150.00	\$ 600.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,040.00	\$663.00	\$600.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,303.00	\$276.36	\$138.18	\$2,717.54