

Date: 5-9-25

Region: 4A

FAC ID: PA027

FEMS/CSS No.: 3156605

Maximo WO No.: 18860



Asset #: [ ]

Priority: 3

**Original Work Request:**

Repair air compressor. Air compressor needs to have a new motor starter installed as the unit can't build up pressure. Tech is aware of the issue and requested a work order be submitted.

**Description of Repairs Needed:**

Proposal is to remove the non working motor starter and replace with new.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Mag Motor Starter, Electronic 208V (14EUE32AD)	1	\$ 891.99	\$ 891.99
Freight	1	\$ 75.00	\$ 75.00
Misc (wire nuts, shop supplies, etc.)	1	\$ 50.00	\$ 50.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$1,016.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,366.99	\$164.04	\$82.02	\$1,613.05