

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Repair exterior building mounted light fixture. Repair building light on the left side of the drill hall inside the fenced in area as it is very dim and continues to blink. Bucket truck will be needed

**Description of Repairs Needed:**

Replace one dusk till dawn light on exterior building using bucket truck for access.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	2	\$ 105.00	\$ 210.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Lights (71W Dusk Till Dawn - LT M-CTKRV3B)	1	\$ 200.00	\$ 200.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
Bucket Truck	2	\$ 105.00	\$ 210.00
			\$ -
			\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$210.00	\$200.00	\$210.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$620.00	\$74.40	\$37.20	\$731.60