

Date: 3-18-25

Region: 4A

FAC ID: PA035

FEMS/CSS No.: 3030867

Maximo WO No.: 18013



Asset #:

Priority: 1

Original Work Request:

Replace copper water lines broken during freeze temperatures related to repair of Reznor heater in Bay 2.

Description of Repairs Needed:

Proposal is to replace copper water lines at PA035. Statement of work to include drain system, replace copper water lines and refill system. The process will include bleeding out all air and startup to check for proper operation.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 170.00	\$ 2,720.00
Trip Charge	1	\$ 59.00	\$ 59.00
			\$ -

Material List:

	Quantity	Cost	Total
Miscellaneous Copper fittings/pipe	1	\$ 1,470.00	\$ 1,470.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$2,779.00	\$1,470.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,249.00	\$509.88	\$254.94	\$5,013.82