

Date: 05-16-25

Region: 4A

FEMS/CSS No.: 3071481

FAC ID: PA035

Maximo WO No.: 19145

Asset #:

Priority: 3



Original Work Request:

Reair MEP gate - it is out of line, bottom wheel needs replaced and ties at bottom of gate need to be changed from aluminum to steel. These repairs are needed to pass Physical Security Inspection.

Description of Repairs Needed:

Proposal is to replace MEP gate guide wheel and remove aluminum ties and replace with steel ties.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 70.75	\$ 283.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Guide Wheel	1	\$ 80.00	\$ 80.00
Steel Ties (S-13604)	4	\$ 88.44	\$ 353.74
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$283.00	\$433.74	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$716.74	\$86.01	\$43.00	\$845.75