

Date: 9-30-25

Region: 4A

FAC ID: PA035

FEMS/CSS No.: 3313346

Maximo WO No.: 20323



Asset #:

Priority: 2

Original Work Request:

Repair leaking water line in Bay 2 of the motor pool, water is presently turned off.

Description of Repairs Needed:

Proposal is to replace leaking copper pipes in the motor pool.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	12	\$ 100.00	\$ 1,200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
copper tube 3/4IDx20'L (3k029)	1	\$ 111.52	\$ 111.52
Press Union 3/4 (7K5050A)	2	\$ 33.42	\$ 66.84
Press Coupling w/ stop 3/4 (7K5002A)	4	\$ 3.90	\$ 15.60
Tube insulation (6R127S)	4	\$ 17.97	\$ 71.88
sales tax	1	\$ 15.95	\$ 15.95
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
scissor lift	1	\$ 794.95	\$ 794.95
propress	1	\$ 50.00	\$ 50.00
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,200.00	\$281.79	\$844.95

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,326.74	\$279.21	\$139.60	\$2,745.55