

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

Replace building light that is not working outside the side entrance of the Training Bldg

Description of Repairs Needed:

Proposal is to replace LED light outside of Training Bldg

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
LED Wall Pack (E-WPE07A-F50BZ0, 6615 Lumen, 50W)	1	\$ 75.00	\$ 75.00
Photocell (CCR-PHC-0306-GC), 120-277V	1	\$ 19.00	\$ 19.00
Freight	1	\$ 15.00	\$ 15.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$109.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$309.00	\$37.08	\$18.54	\$364.62