

Date: 01-12-26



Region: 4A

FEMS/CSS No.: 3462644

FAC ID: PA035

Maximo WO No.: 20965

Asset #:

Priority: 3

Original Work Request:

The contactors on the air compressor are burnt up and need to be replaced.

Description of Repairs Needed:

Proposal is to replace the motor starter on the compressor. Motor starter has to be replaced because the contactor cannot be purchases separately.

Labor:

| | Labor Hrs | Labor Rate | Total |
|----------|-----------|------------|-----------|
| Tech (1) | 2.5 | \$ 100.00 | \$ 250.00 |
| | | | \$ - |
| | | | \$ - |

Material List:

| | Quantity | Cost | Total |
|---|----------|-----------|-----------|
| Motor Starter (8911DP42V09) 2P, 40A, 208/240V | 1 | \$ 498.41 | \$ 498.41 |
| Freight | 1 | \$ 50.00 | \$ 50.00 |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |

Equipment List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | | \$ - |
| | | | \$ - |
| | | | \$ - |

PM WO History:

Estimate Summary:

| Labor | Material | Equipment |
|----------|----------|-----------|
| \$250.00 | \$548.41 | \$0.00 |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|-----------|---------|---------|----------------|
| \$798.41 | \$95.81 | \$47.90 | \$942.12 |