

Date: 3-24-26



Region: 4A

FEMS/CSS No.: 3535939

FAC ID: PA035

Maximo WO No.: 21615

Asset #:

Priority: 2

Original Work Request:

Water fountain that has abottle filler is not working, sensor eye needs to be replaced.

Description of Repairs Needed:

Replace bottle filler solenoid and ensure proper operation

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	1	\$ 100.00	\$ 100.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Elkay Bottle Filler Solenoid Valve kit (98545C, #140441)	1	\$ 159.99	\$ 159.99
Shipping	1	\$ 15.00	\$ 15.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$100.00	\$174.99	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$274.99	\$33.00	\$16.50	\$324.49