

Date: 7-08-24

Region: 4A

CSS No.: 98391

FAC ID: PA062

Maximo WO No.: 16146



Asset #: [Redacted]

Priority: 3

Original Work Request:

Repair the exhaust fan motor. During the PM inspection technician found that the exhaust fan motor needs to be replaced (Asset #3482).

Description of Repairs Needed:

Replace exhaust fan discovered inoperable during PM inspection. Dispose old unit, wire new unit and verify operations.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 100.00	\$ 800.00
			\$ -

Material List:

	Quantity	Cost	Total
Upblast Exhauster, 1 PH, 1/3 hp (ALX135-UD033EC)	1	\$ 1,699.14	\$ 1,699.14
Freight	1	\$ 100.00	\$ 100.00
Misc (shop supplies, wiring, screws, etc)	1	\$ 50.00	\$ 50.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$800.00	\$1,849.14	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,649.14	\$317.90	\$158.95	\$3,125.99