

Date: 8-28-25

Region: 4A

FEMS/CSS No.: 3189942

FAC ID: PA062

Maximo WO No.: 20067

Asset #:

Priority:  3



**Original Work Request:**

Per inspection by Grunua, the bypass buttons on both FACPS were blinking constantly in the Training Center. Recommend troubleshooting to identify the issue.

**Description of Repairs Needed:**

Repaired Uduct trouble as well as trouible on panel

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 154.00	\$ 616.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$616.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$616.00	\$73.92	\$36.96	\$726.88