

Date: 3-6-24

Region: 4A

FAC ID: PA063

CSS No.: 96805

Maximo WO No.: 15193

Asset #:

Priority: 3



Original Work Request:

The wall heater in the ladies room is making a loud grinding noise and there is no heat blowing out.

Description of Repairs Needed:

Replace motor for K84 GR 4E449 Beacon Morris wall heater in ladies room. Special order quote...shipping ETA 5 days from order.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -

Material List:	Quantity	Cost	Total
MFR Part #: BMKR02020-002 MOTR/WHL	1	\$ 174.75	\$ 174.75
shipping/freight	1	\$ 25.00	\$ 25.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$199.75	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$599.75	\$71.97	\$35.99	\$707.71