

Date: 12-15-23

Region: 4A

CSS No.: 95974

FAC ID: PA118

Maximo WO No.: 14533

Asset #:

Priority: 3



Original Work Request:

Repair overhead door (bay door #9) as it is not operating properly. Door sticks at a certain point when going up and down.

Description of Repairs Needed:

Lubricated, adjusted tensioners. Discovered clutch needed adjustment

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 113.00	\$ 452.00
			\$ -

Material List:

	Quantity	Cost	Total
Misc Truck Supplies	1	\$ 21.90	\$ 21.90
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$452.00	\$21.90	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$473.90	\$56.87	\$28.43	\$559.20