

Date: 2-15-24

Region: 4A

FAC ID: PA118

CSS No.: 96439

Maximo WO No.: 14984

Asset #:

Priority: 2



Original Work Request:

Repair overhead door on enclosed wash rack building. There is no power to the overhead door

Description of Repairs Needed:

Replace monitored electric edge on wash rack door.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2) - Initial Investigation	6	\$ 119.50	\$ 717.00
Trip Charge - Initial Investigation	1	\$ 213.00	\$ 213.00
Tech (2) - Repair	4	\$ 119.50	\$ 478.00
Trip Charge - Repair	1	\$ 213.00	\$ 213.00

Material List:	Quantity	Cost	Total
EIS (fuel surcharge) - Initial investigation	1	\$ 10.00	\$ 10.00
EIS (fuel surcharge) - Repair	1	\$ 10.00	\$ 10.00
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
ME123 Miller Electric Edge 30'2"	1	\$ 1,056.00	\$ 1,056.00
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,621.00	\$20.00	\$1,056.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,697.00	\$323.64	\$161.82	\$3,182.46