

Date: 05-10-24

Region: 4A

CSS No.: 97876

FAC ID: PA118

Maximo WO No.: 15623

Asset #:

Priority: 3



Original Work Request:

Repair CAC reader on Warehouse main door. Also requesting hood cover instead of plastic

Description of Repairs Needed:

Repair CAC Reader and weather shield, and replace wiring on Warehouse Main Man Door at Conneaut Lake USARC.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 95.00	\$ 1,520.00
			\$ -

Material List:

	Quantity	Cost	Total
Biometric Card Reader (900W2030-WGPON)	1	\$ 1,550.00	\$ 1,550.00
Heavy Duty Weathershield Cover	1	\$ 275.00	\$ 275.00
500 ft of 18-12 Wiring @ 1.18/ft	500	\$ 1.18	\$ 590.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,520.00	\$2,415.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,935.00	\$472.20	\$236.10	\$4,643.30