

Date: 6-17-24

Region: 4A

FAC ID: PA118

CSS No.: 98140

Maximo WO No.: 16124

Asset #:

Priority: 1



Original Work Request:

Repair diesel engine for fire pump - fuel injector is not working. Engine can't be started so we have no fire suppression. Engine is manufactured by Clark.

Description of Repairs Needed:

Per this proposal, Grunau fire pump specialists will trouble shoot and investigate status of (1) diesel fire pump at PA118. Specialists will attempt to repair fire pump same day if able. Please note that crew may determine additional repair materials are needed and if this is the case, a seconde separate proposal for an additinal return trip will be provided. Work completed on 6/5/24 (under KO Appvl, NTE \$2500) - Contractor bled air, primed and everything ran fine. Ran manually and auto...no additional work needed at this time.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2)	6	\$ 144.00	\$ 864.00
Fire Pump Specialist Mobilization	1	\$ 250.00	\$ 250.00

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,114.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,114.00	\$133.68	\$66.84	\$1,314.52