

Date: 7-02-24

Region: 4A  
FAC ID: PA118

CSS No.: 98356  
Maximo WO No.: 16140

Asset #:

Priority: 2



Original Work Request:

Repair FDC identified during 5-Yr hydrostatic testing. Inspection discovered that the FDC connection is leaking to Siamese connection. Service request is to repair connection and retest for compliance.

Description of Repairs Needed:

Proposal includes providing a new brass straight Siamese connectin with (2) 2-1/2" female NPT inlets. Retest connections after repairs are completed. Work to be completed to all applicable NFPA Standards and local codes. Exclusions noted on contractor quote.

Labor:	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 144.00	\$ 2,304.00
			\$ -

Material List:	Quantity	Cost	Total
New Siamese FDC Connection	1	\$ 1,050.00	\$ 1,050.00
Threaded Piping Spool Replacement	1	\$ 594.00	\$ 594.00
Freight	1	\$ 400.00	\$ 400.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$2,304.00	\$2,044.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,348.00	\$521.76	\$260.88	\$5,130.64