

Date: 11-15-24

Region: 4A
FAC ID: PA118

FEMS/CSS No.: 2935250
Maximo WO No.: 17098

Asset #:

Priority: 2



Original Work Request:

Repair exhaust fan #2 in the low bya that controls exhaust hoses (5, 6, 7, 8, 12). The unit is making a loud noise when it operates and will not function.

Description of Repairs Needed:

Proposal is to replace the motor to the exhaust fan. Work will be performed by in-house staff.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 100.00	\$ 800.00
			\$ -

Material List:

	Quantity	Cost	Total
Motor (D10P2D Motor GP 3PH 215T 10HP 1800 RPM			\$ -
208-230/460V ODP 23.8AMP	1	\$ 984.80	\$ 984.80
Freight	1	\$ 235.00	\$ 235.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
Lift	1	\$ 945.00	\$ 945.00
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$800.00	\$1,219.80	\$945.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,964.80	\$355.78	\$177.89	\$3,498.46