

Date: 2-13-2025

Region: 4A

FEMS/CSS No.: 3031114

FAC ID: PA118

Maximo WO No.: 18254

Asset #:

Priority: 2



Original Work Request:

High bay overhead door #16 is not working properly. It is making a very loud noise when opened and closed, like it is not on the track properly.

Description of Repairs Needed:

Proposal is to replace sheave pulleys on door #16, includes previous service charges to investigate.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2) (Investigate)	3.5	\$ 119.50	\$ 418.25
Trip Charge (Investigate)	1	\$ 213.00	\$ 213.00
Tech (2) (Repair)	6	\$ 119.50	\$ 717.00
Trip Charge (Repair)	1	\$ 213.00	\$ 213.00

Material List:

	Quantity	Cost	Total
Lubricant (HVY ST 400, 15 oz) - Investigate	0.1	\$ 23.38	\$ 2.34
Economic Surcharge - Investigate	1	\$ 10.00	\$ 10.00
Lubricant (HVY ST 400, 15 oz) - Repair	0.1	\$ 23.38	\$ 2.34
Economic Surcharge - Repair	1	\$ 10.00	\$ 10.00
Sheave Pulley Door Pulley (4B5V80)	2	\$ 306.26	\$ 612.52
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 290.00	\$ 290.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,561.25	\$637.20	\$290.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,488.45	\$298.61	\$149.31	\$2,936.37