

Date: 2-14-2025

Region: 4A

FEMS/CSS No.: 3031283

FAC ID: PA118

Maximo WO No.: 18257

Asset #:

Priority: 2



Original Work Request:

Overhead bay door #13 is acting erratic and will not open or close all the way. Motor continues to run when door isn't moving. Door is presently closed.

Description of Repairs Needed:

Replace LSLO top shaft and both left hand sides of center couplings and key stock.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2) - investigate	2.5	\$ 119.50	\$ 298.75
Trip Charge - investigate	1	\$ 213.00	\$ 213.00
Tech (2) - repair	6	\$ 119.50	\$ 717.00
Tech (2) - repair	1	\$ 213.00	\$ 213.00

Material List:

	Quantity	Cost	Total
Lubricant (HVY WT 400) - investigate and repair	0.2	\$ 23.38	\$ 4.68
Economic Surcharge - investigate and repair	2	\$ 10.00	\$ 20.00
Shaft, 1" Solid (1127)	10	\$ 15.47	\$ 154.70
Coupling Assembly, 1" Shaft (168)	1	\$ 117.00	\$ 117.00
Key Stock, 1/4"x1/4"x3"	6	\$ 2.38	\$ 14.28
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Scissor Lift	2	\$ 290.00	\$ 580.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,441.75	\$310.66	\$580.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,332.41	\$279.89	\$139.94	\$2,752.24