

Date: 5-22-25

Region: 4A

FEMS/CSS No.: 3114225

FAC ID: PA118

Maximo WO No.: 19165

Asset #:

Priority: 2



Original Work Request:

Repair exterior pole lights. Repair 3 pole lights (11, 8 and 5) in the MEP. Supervisor has a drawing of which lights that are not working. A bucket truck will be needed to make the repairs. This is physical security issue. Recommended contractor: C&K

Description of Repairs Needed:

Proposal is to repair exterior pole lights at PA118 (#s11, 8 and 5).

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	7	\$ 115.00	\$ 805.00
Service Call	1	\$ 99.00	\$ 99.00
			\$ -

Material List:

	Quantity	Cost	Total
Photocells	3	\$ 27.51	\$ 82.53
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
Bucket Truck	2	\$ 50.00	\$ 100.00
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$904.00	\$82.53	\$100.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,086.53	\$130.38	\$65.19	\$1,282.11