

Date: 1-2126

Region: 4A

FEMS/CSS No.: 3496722

FAC ID: PA118

Maximo WO No.: 21187

Asset #:

Priority:  1



**Original Work Request:**

Propane leak in AMSA around overhead door #9 where we found that there is a gas burner located for the radiant heaters, this might be a possible location of gas leak. We have asked the propane provider Amerigas if they can put a sniffer on the location to identify the exact location.

**Description of Repairs Needed:**

Proposal is for CMI Tech responding to emergency call and determining location and fix for the propane leak. Unit was turned off until parts could be procured and tech returned to follow up with clamps for the fixture.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1) - Initial Response	1.5	\$ 100.00	\$ 150.00
Tech (1) - Follow up response	2	\$ 100.00	\$ 200.00
			\$ -

**Material List:**

	Quantity	Cost	Total
Coupling - 4"	1	\$ 11.63	\$ 11.63
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$350.00	\$11.63	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$361.63	\$43.40	\$21.70	\$426.72