

Date: 4-1-26



Region: 4A

FEMS/CSS No.: 3576833

FAC ID: PA118

Maximo WO No.: 21655

Asset #:

Priority: 2

Original Work Request:

Replace ceiling tiles in hallway that have been damaged by a leaking AHU. Tiles are provided by the facility.

Description of Repairs Needed:

Proposal is for labor to replace ceiling tiles, including changing those around fire protection devices.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3	\$ 100.00	\$ 300.00
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -

Material List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$500.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$500.00	\$60.00	\$30.00	\$590.00