

Date: 7/19/2023

Region: 4A
FAC ID: PA209

CSS No.: 94336
Maximo WO No.: 13429

Asset #:

Priority: 2



Original Work Request:

Repair ciruculating pump in the OMS building. While on site PM technician found that the B&G circulation pump in the OMS building was leaking water and needs to be replaced.

Description of Repairs Needed:

Replace circulating pump and flange. Check operations

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	2.5	\$ 100.00	\$ 250.00
			\$ -

Material List:

	Quantity	Cost	Total
Potable Circualting Pump, Flanghed 1/6 HP (#1BL003LF)	1	\$ 742.43	\$ 742.43
Flange Kit - B&G (#118368)	1	\$ 12.61	\$ 12.61
Shop supplies	1	\$ 20.00	\$ 20.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$775.04	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,025.04	\$123.00	\$61.50	\$1,209.55