

Date: 4-16-25



Region: 4A

FEMS/CSS No.: 3114268

FAC ID: PA209

Maximo WO No.: 18776

Asset #:

Priority: 2

Original Work Request:

Replace 4 HP motor in return air fan (RA-1). The spare motor is on site at the facility and the old motor is to be removed and new motor installed. In addition, the contractor needs to install a grease fitting where the shipping plug is located on the new motor installed in RA-1.

Description of Repairs Needed:

Proposal is to remove old motor and replace with customer supplied motor for RA-1. Old motor to be removed from site. Check motor startup and check for proper operation.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	16	\$ 170.00	\$ 2,720.00
Trip Charge	1	\$ 360.00	\$ 360.00
			\$ -

Material List:

	Quantity	Cost	Total
Grease fitting	1	\$ 30.00	\$ 30.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$3,080.00	\$30.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,110.00	\$373.20	\$186.60	\$3,669.80