

Additional Funding Request

NY127	CSS# 27021 WO# 10668 Asset# NA								
Description of Repairs	Labor and travel to conduct PM on Vault Door (includes Combo Change)								
Diagnosis: Initial Work Order	Need to have Vault combination changed.								
Diagnostic Fee	\$0								
Additional Labor Cost to Perform Repairs	<p>\$ 512.50</p> <p>TW Labor Flat fee \$250</p> <p>Travel 3.5 hrs x 75 262.50</p>								
Additional Material Cost to Perform Repairs	<p>\$ 0.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;"></td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> <td style="width: 25%;"></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </table>								
Total Cost of Repair	\$ 512.50								

Tick Tock Safe and Lock

PO Box 311
Liverpool, NY 13088
(315) 944-0532
service@ticktocksafeandlock.com
http://www.ticktocksafeandlock.com

**TICK TOCK**
SAFE AND LOCK

Estimate

ADDRESS

Tidewater Inc.
3761 Attucks Dr
Powell, OH 43065

ESTIMATE # 201023-01**DATE** 10/23/2020**WORK ORDER/PO NUMBER**

NY127-2020PM

DATE	DESCRIPTION	QTY	RATE	AMOUNT
	Conduct PM on GSA Vault Door (includes combination change)	1	250.00	250.00T
	Travel	3.50	75.00	262.50T
			SUBTOTAL	512.50
			TAX	41.00
			TOTAL	\$553.50

Accepted By

Accepted Date