

Date: 7/27/2023

Region: 4C
FAC ID: WV046

CSS No.: 93229
Maximo WO No.: 13362

Asset #: NA

Priority: Routine



Original Work Request:

The fan motors in tool room and mechanical room are not working need to be repaired

Description of Repairs Needed:

Labor and material to a.) install 1862H Motor Cond 48FRM 1/2HP 1075RPM 208-230V ISP REV TEAO b.) and install 60884501 FAN BLADE 26" 28-DEG 4-BLADE CW 1/2" HUB 1HP 7440CFM

Labor	Labor Hrs	Labor Rate	Total
Technician	2	\$ 100.00	\$ 200.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
1862H 48FRM 1/2HP 1075RPM 208-230V ISP REV TEAO	1	\$ 193.41	\$ 193.41
60884501 26" 28-DEG 4-BLADE CW 1/2" HUB 1HP 7440CFM	1	\$ 98.91	\$ 98.91
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$292.32	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$492.32	--	--	\$492.32

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.

6625 Selknick Drive, Suite A

Elkridge, MD 21075

Prepared for:

CMI Management, Inc.

5285 Shawnee Road Suite 510

Alexandria, VA 22312-2334

Date: 7/27/2023

CSS #: 93229

FAC ID: WV046

WO #: 13362

DESCRIPTION OF WORK

Labor and material to a.) install 1862H Motor Cond 48FRM 1/2HP 1075RPM 208-230V ISP REV TEAO b.) and install 60884501 FAN BLADE 26" 28-DEG 4-BLADE CW 1/2" HUB 1HP 7440CFM

LABOR	QTY	UNIT/RATE	TOTAL
Technician	2	\$100.00	\$200.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
1862H 48FRM 1/2HP 1075RPM 208-230V ISP REV TEAO	1	\$193.41	\$193.41
60884501 26" 28-DEG 4-BLADE CW 1/2" HUB 1HP 7440CFM	1	\$98.91	\$98.91
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$200.00
	MATERIAL TOTAL		\$292.32
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$492.32

Accepted By: _____

Date: _____