

Date: 10/23/2023

Region: 4A  
FAC ID: NY070

CSS No.: 93869  
Maximo WO No.: 14115

Asset #: NA

Priority: Urgent



**Original Work Request:**

Door does not meet Emergency Egress or ADA Requirements. As noted in the Safety Inspection report dated Aug. 2021. Remove 2 - 23 inch wide doors and replace with 1 door minimum 32 inches wide. Install side light to make up the distance to meet frame. Door shall be primed and painted on both sides. See attached pictures

**Description of Repairs Needed:**

Labor and material to a.) remove and dispose of existing 23" doors and frame. b.) Prep and install new frame and 48" door unit. c.) Includes: closer, kick plate, lockset and panic bar compatible with existing core. Door to be painted to match existing doors.

Labor:	Labor Hrs	Labor Rate	Total
Technician	16	\$ 100.00	\$ 1,600.00
			\$ -

Material List:	Quantity	Cost	Total
Misc Material	1	\$ 3,270.00	\$ 3,270.00

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA
----

**Estimate Summary:**

Labor	Material	Equipment
\$1,600.00	\$3,270.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$4,870.00	\$584.40	\$292.20	\$5,746.60

**HUNOLD CONTRACTING INC.**

72 PENDERGAST ROAD

PHOENIX, NY 13135

Cell # 315-247-5898

Customer:

Tidewater Attn: Karlee

6625 Selmick Dr., Suite A

Elkridge, MD 21075

**ESTIMATE****10/23/23**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	CSS 93869, WO 14115, NY070 Webster, NY  Remove and dispose of existing 23" doors and frame. Prep and install new frame and 48" door unit. Includes: closer, kick plate, lockset and panic bar compatible with existing core. Door to be painted to match existing doors.  Material: (\$3270) Labor: (16 hours @ \$100/ hr.) =\$1600	<b>4870.00</b>
<b>Sub total</b>		<b>4870.00</b>
<b>Sales Tax</b>		<b>N/A</b>
<b>Total</b>		<b>4870.00</b>

**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_**Signature**\_\_\_\_\_ **Date**\_\_\_\_\_