

Date: 7/26/2023

Region: 4C  
FAC ID: WV020

CSS No.: 94412  
Maximo WO No.: 13626

Asset #: NA

Priority: Urgent



**Original Work Request:**

In training building in mechanical room. This pump has failed and cannot be repaired. It needs replaced to make the hot water tanks work properly.

**Description of Repairs Needed:**

Labor and material to a.) replace the Booster Pump 106185 PUMP BOOSTER IRON 1/12HP 115V 1PH NPTP CONN

Labor	Labor Hrs	Labor Rate	Total
Technician	3	\$ 100.00	\$ 300.00
		\$ -	\$ -

Material List:	Quantity	Cost	Total
06185 PUMP BOOSTER IRON 1/12HP 115V 1PH NPTP CONN	1	\$ 795.93	\$ 795.93
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$300.00	\$795.93	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,095.93	--	--	\$1,095.93

Note: G&A and Fee are not applied on top of work performed by Tidewater.



Prepared by:

Tidewater, Inc.  
6625 Selkirk Drive, Suite A  
Elkridge, MD 21075

Prepared for:

CMI Management, Inc.  
5285 Shawnee Road Suite 510  
Alexandria, VA 22312-2334

Date: 7/26/2023 CSS #: 94412  
FAC ID: WV020 WO #: 13626

DESCRIPTION OF WORK			
Labor and material to a.) replace the Booster Pump 106185 PUMP BOOSTER IRON 1/12HP 115V 1PH NPTP CONN			

LABOR	QTY	UNIT/RATE	TOTAL
Technician	3	\$100.00	\$300.00
		\$0.00	\$0.00
MATERIAL	QTY	UNIT/RATE	TOTAL
06185 PUMP BOOSTER IRON 1/12HP 115V 1PH NPTP CONN	1	\$795.93	\$795.93
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
EQUIPMENT	QTY	UNIT/RATE	TOTAL
		\$0.00	\$0.00
		\$0.00	\$0.00
		\$0.00	\$0.00
SUB-TOTAL COSTS:	LABOR TOTAL		\$300.00
	MATERIAL TOTAL		\$795.93
	EQUIPMENT TOTAL		\$0.00
TOTAL COST:			\$1,095.93

Accepted By: \_\_\_\_\_

Date: \_\_\_\_\_