

Date: 7/24/2023

Region: 4C
FAC ID: WV046

CSS No.: 93985
Maximo WO No.: 13377

Asset #: NA

Priority: Urgent



Original Work Request:

Rollup door in supply storage has a bad bump stop safety, needs to be replaced. The bump stop is the strip that is installed on the bottom of the door that stops it from closing if object in path of door

Description of Repairs Needed:

Labor and material to a.) replace 11 feet of Pneumatic Hose.

Labor:

	Labor Hrs	Labor Rate	Total
Technician	2	\$ 90.00	\$ 180.00
			\$ -

Material List:

	Quantity	Cost	Total
Feet of Pneumatic Hose	11	\$ 4.00	\$ 44.00
Trip Charge	1	\$ 150.00	\$ 150.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$180.00	\$194.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$374.00	\$44.88	\$22.44	\$441.32

American Garage Door, LLC **Phone 304-592-0936**
6909 Shinnston Pike **Fax 304-592-3430**
Shinnston, WV 26431

Invoice No.

72023

INVOICE

Customer

Name Tidewater, Inc.
Address 6625 Selnick Dr., Suite A
City Elkridge State MD ZIP 21075
Phone 410-540-8700

Misc

Date 7/20/2023
Cust PO _____
Rep _____
FOB _____

Qty	Description	Unit Price	TOTAL
	4603 Camden Ave Parkersburg, WV Karlee Demain 724-678-6067 Roll up door in supply storage safety edge not working		
11	feet of Pneumatic Hose	\$ 4.00	\$ 44.00
1	trip charge (in Area)	\$ 150.00	\$ 150.00
2	Commercial Hours Labor 2 men	\$ 90.00	\$ 180.00

SubTotal	\$ 374.00
Shipping	
Tax Rate(s)	6.00%
	\$ 22.44
TOTAL	\$ 396.44

Payment

Comments _____
Name _____
CC # _____
Expires _____

Office Use Only

Payment Due Upon Job Completion! 1.5% Per Month Interest Charges Will Incur After 30 Days!

Thanks