

Date: 9/6/2023

Region: 4C
FAC ID: WV020

CSS No.: 94986
Maximo WO No.: 13859

Asset #: NA

Priority: Urgent



Original Work Request:

Repair vault door - there's some issue with the door connection that's causing the alarm to go off.

Description of Repairs Needed:

Labor to a.) diagnose the connection issues being experienced with the Vault Door and repair if possible while on site at the Jane Lew,

Labor:

	Labor Hrs	Labor Rate	Total
Technician	16	\$ 85.00	\$ 1,360.00
			\$ -

Material List:

	Quantity	Cost	Total
Balance Magnetic Switch (BMS)	1	\$ 346.88	\$ 346.88
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

NA

Estimate Summary:

Labor	Material	Equipment
\$ 1,360.00	\$ 346.88	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,706.88	\$204.83	\$102.41	\$2,014.12

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 2337
DATE 09/06/2023

P.O. NUMBER

Jane Lew WV020 Diag. Vault Door

	ACTIVITY	QTY	AMOUNT
09/06/2023	Services Jane Lew, WV USARC WV020 Diagnose & Repair if possible Vault Door CSS#94986 WO#13859	1	1,706.88

Dear Ms. Demain,

As per your request, LoCurrent Systems is pleased to provide a quotation to diagnose the connection issues being experienced with the Vault Door and repair if possible while on site at the Jane Lew, WV USARC WV020.

Cost Breakdown:

(2) men 8 hrs @
\$85.....\$1,360.00
(1) Balance Magnetic Switch
(BMS).....\$346.88

Grand
Total.....\$1,706.88

The cost for the above mentioned work is
\$1,706.88.

If acceptable, please do not hesitate to contact us so we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

ACTIVITY	QTY	AMOUNT
Sincerely, Antonietta LoRusso		
	TOTAL	\$1,706.88

Accepted By

Accepted Date