



CUSTOMER QUOTATION NO. 1033

CMI Management, Inc.
5285 Shawnee Road Suite #510
Alexandria VA 22312

Quote Name: 17317
Quote No: 1033
Site: MD066 Fox Tail Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 05/11/2022
Valid For: 30 Day(s)

WO#: 17317

CSS Ticket Number: 98

Problem: Wall pack light above the Mechanical Room of the OMS building is flashing.

S&S proposes to remove and replace the faulty emergency ballast in the wall pack light located in the mechanical room of the OMS building.

*Lead time 3-4 weeks.

Service

Item	Quantity	Unit Price	Total
Emergency LED Driver	1.00	\$522.64	\$522.64
Shipping	1.00	\$100.00	\$100.00
Diagnosis Fee	1	\$300.00	\$300.00
Electrical Labor Rate	6	\$100.00	\$600.00
Sub-Total ex Tax			\$1,522.64
Tax			\$0.00
Total inc Tax			\$1,522.64

Labor	\$900.00
Materials	\$622.64
Sub-Total ex Tax	\$1,522.64
Tax	\$0.00
Total inc Tax	\$1,522.64