

Date: 1/3/2024

Region: 4C

CSS No.: 94671

FAC ID: VA039

Maximo WO No.: 14101

Asset #:

Priority: 3



Original Work Request:

Post inspection crane repair to to replace pins mounting hoist to trolley and replace/repair squeaking discs glazed over. Correct collectors that are out of alignment, worn/dead spots. Repair recommended by U.S. Crane during inspection completed in July 2023.

Description of Repairs Needed:

Address items identified during annual inspection services conducted in July. Quote #44076P - Repairs needed on hoist to replace hoist brake discs and repair conductor issues (quote based on using customer's scissor lift on site). Quote #44476P - Recommendation to inspect trolley to hoist and replace connections pins due to age (quote based on using customer's telehandler on site). Note Limitations/Exceptions: proposal specific to findings in attached inspection report only (Annual Inspection Report attached)

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	24	\$ 156.25	\$ 3,750.00
Tech (2)	24	\$ 145.83	\$ 3,499.92
Tech (1)	12	\$ 155.83	\$ 1,869.96

Material List:

	Quantity	Cost	Total
Disc Lining (#25719U)	2	\$ 690.95	\$ 1,381.90
Conductor Bar	1	\$ 1,920.15	\$ 1,920.15
Hangar Pin (2981751U)	2	\$ 177.53	\$ 355.06
UPS Delivery Charge for Disc	1	\$ 18.60	\$ 18.60
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Telehandler Lift Rental	1	\$ 1,825.00	\$ 1,825.00
Fork Lift Rental & Off Load	1	\$ 2,295.00	\$ 2,295.00
Scissor Lift	1	\$ 395.00	\$ 395.00

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$9,119.88	\$3,675.71	\$4,515.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$17,310.59	\$2,077.27	\$1,038.64	\$20,426.50