

Additional Funding Request

Site: WV024	WO#5816	CSS # 15543	Asset# NA
Description of Repairs	Repair Flag Pole Lights		
Diagnosis: Initial Work Order CSS# 15543	Repair Flag Pole Lights		
Explanation of Additional Costs for Repairs	Labor and material to replace window lock mechanisms		
Additional Labor Cost to Perform Repairs	7 hours x \$85.00- \$595		
Additional Material Cost to Perform Repairs	Lift Rental 2 Days- \$300 Photocell/LED- \$306.80		
Total Cost of Repair	\$1,201.80		

TRI-CITY ELECTRICAL CONTRACTING, INC. WV024246

PROPOSAL

Kingwood Exterior Lights

Diagnosis:

- (1) New Photocell is needed for Round LED Fixture
 - Part# Cooper 1011-6424 SL3120
- (1) New LED Flood is needed for Flagpole Fixture
 - Part# Lumark Night Falcon NFFLD-S-C15-T-UNIV
- (1) New Switch and Cover is needed

Diagnosis Includes:

- Lift Rental
- Trouble Shooting (2) Light Fixtures and Switching

Diagnosis Amount Due:

Lift Rental	\$150.00
Labor – 3.5 Hrs @ \$85.00	<u>\$297.50</u>
	\$447.50

Cost Proposal

Lift Rental	\$150.00
Material	
• Twist in Photocell (1) @ \$16.80	\$16.80
• LED Flood Light (1) @ \$290.00	\$290.00
Labor – 3.5 Hrs @ \$85.00	<u>\$297.50</u>
	\$754.30



Proposal Submitted by: _____

