

**Region:** 5

**Location:** DE007

**CSS #** 31520

**Maximo Work Order No.:** 14545

**Asset #:** NA

**Date Issued:** 8/10/21 REVISED 5/17/22

**Original Description:** Wall pack exhaust fan- asset 1057 Switch is broken and not getting power to the switch. - \$250 PM will apply

**Repairs Needed:**

S&S proposes to remove and replace the slow running fan motor in exhaust fan 1057. S&S will replace the faulty RIB and kill switch in exhaust fan 1058. S&S will then complete a system run to ensure everything is working properly.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials(See attached quote with detail)	--	--	\$1,311.99	--	\$1,311.99
--	NA	S&S Labor including Diagnostic	29	\$100.00			\$2,900.00
--	NA	TW Oversite	4	\$80.00	--	--	\$320.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate Includes \$250 PM Credit
33	\$3,220.00	\$1,311.99		\$4,531.99	106%	\$4,553.91

